

### Goodman

Direct Replacement For	
SK5B46GF0001S	B4833000
Item ID	48331
Stack Size (in.)	1.25
Volts	115
RPM	3200
Amps	1.80
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic
Includes	Rubber Boot



### Goodman

Direct Replacement For	
SK5B46GF0001S	B48330001
Item ID	48332
Stack Size (in.)	1.25
Volts	115
RPM	3200/2800
Amps	1.80/1.10
Speeds	2
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic
Includes	Rubber Boot



### Goodman

Direct Replacement For	
11009001	11009002 11009003
Item ID	66003
Watts	30
Volts	115
RPM	3250
Amps	0.92
Speeds	1
Type	PSC
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
0131M00003	0131M00003P
Item ID	66202
Watts	56
Volts	115
RPM	3000
Amps	1.13/0.56
Speeds	2
Type	PSC
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
0131M00002P	0131M00002S
Item ID	66002
Stack Size (in.)	1.5
Volts	115
RPM	3000
Amps	1.20
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic
Includes	Gasket



### Goodman

Direct Replacement For	
071M00000	
Item ID	66071
Stack Size (in.)	1.5
Volts	120
RPM	3000
Amps	2.8
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
D9868602	
Item ID	66743
H.P.	1/24
Volts	115
RPM	3000
Amps	1.5
Speeds	1
Type	Shaded Pole
Bearings	Sleeve
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
B4059000	J238-112-11195 7002-3036 J238-11195
Item ID	66590
H.P.	1/30
Volts	115
RPM	3000
Amps	1.50
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
0271F00126	702112495
Item ID	66126
H.P.	1/32
Volts	115
RPM	3300
Amps	1.0
Speeds	2
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
0131G00000P	
Item ID	66000
Stack Size (in.)	1.5
Volts	230
RPM	3000
Amps	1.4
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
B1859005	J238-11128
Item ID	66005
H.P.	1/30
Volts	115
RPM	3000
Amps	1.60
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
B29590005	
Item ID	66959
H.P.	1/30
Volts	208/230
RPM	3000
Amps	0.60/0.56
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
0131G00007	0131G00093S
Item ID	66007
H.P.	1/50
Volts	230
RPM	3000
Amps	.24
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
0131G00009	
Item ID	66009
H.P.	1/32
Volts	230
RPM	3000
Amps	0.24
Speeds	3
Type	PSC
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
B4059000	7002-3036
Item ID	A182
H.P.	1/35
Volts	115
RPM	3125
Amps	1.20
Speeds	1
Type	Shaded Pole
Bearings	Sleeve
Enclosure	Open
Hertz	60
Overload	Automatic



### Goodman

Direct Replacement For	
B1859000	B18590005
Item ID	82483
H.P.	1/50
Volts	115
RPM	3000
Amps	0.9
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic

