

Goodman

Direct Replacement For	
SK5B46GF0001S	B4833000
Item ID	48331
Stack Size (in.)	1.25
Volts	115
RPM	3200
Amps	1.80
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic
Includes	Rubber Boot



Goodman

Direct Replacement For	
SK5B46GF0001S	B48330001
Item ID	48332
Stack Size (in.)	1.25
Volts	115
RPM	3200/2800
Amps	1.80/1.10
Speeds	2
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic
Includes	Rubber Boot



Goodman

Direct Replacement For	
11009001	11009002 11009003
Item ID	66003
Watts	30
Volts	115
RPM	3250
Amps	0.92
Speeds	1
Type	PSC
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
0131M00003	0131M00003P
Item ID	66202
Watts	56
Volts	115
RPM	3000
Amps	1.13/0.56
Speeds	2
Type	PSC
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
0131M00002P	0131M00002S
Item ID	66002
Stack Size (in.)	1.5
Volts	115
RPM	3000
Amps	1.20
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic
Includes	Gasket



Goodman

Direct Replacement For	
071M00000	
Item ID	66071
Stack Size (in.)	1.5
Volts	120
RPM	3000
Amps	2.8
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
D9868602	
Item ID	66743
H.P.	1/24
Volts	115
RPM	3000
Amps	1.5
Speeds	1
Type	Shaded Pole
Bearings	Sleeve
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
B4059000	J238-112-11195 7002-3036 J238-11195
Item ID	66590
H.P.	1/30
Volts	115
RPM	3000
Amps	1.50
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
0271F00126	702112495
Item ID	66126
H.P.	1/32
Volts	115
RPM	3300
Amps	1.0
Speeds	2
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
0131G00000P	
Item ID	66000
Stack Size (in.)	1.5
Volts	230
RPM	3000
Amps	1.4
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
B1859005	J238-11128
Item ID	66005
H.P.	1/30
Volts	115
RPM	3000
Amps	1.60
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
B29590005	
Item ID	66959
H.P.	1/30
Volts	208/230
RPM	3000
Amps	0.60/0.56
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
0131G00007	0131G00093S
Item ID	66007
H.P.	1/50
Volts	230
RPM	3000
Amps	.24
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
0131G00009	
Item ID	66009
H.P.	1/32
Volts	230
RPM	3000
Amps	0.24
Speeds	3
Type	PSC
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
B4059000	7002-3036
Item ID	A182
H.P.	1/35
Volts	115
RPM	3125
Amps	1.20
Speeds	1
Type	Shaded Pole
Bearings	Sleeve
Enclosure	Open
Hertz	60
Overload	Automatic



Goodman

Direct Replacement For	
B1859000	B18590005
Item ID	82483
H.P.	1/50
Volts	115
RPM	3000
Amps	0.9
Speeds	1
Type	Shaded Pole
Bearings	Ball
Enclosure	Open
Hertz	60
Overload	Automatic

