

**Mid Continent**



HP	RPM	Speeds	Volts	Amps	Stock No.	Alt.	Rot.	Capacitor	Shaft Diameter & Length	Motor Dia.	"A" Dim.	Conn. Dia. No.	Cross Reference	Notes
1/30	3000	1	115	1.1	357		CCWLE	Shaded Pole	1/4" x 1-1/2"	3-3/8"	4-3/4"		JA1M069NV	
1/30	1550	1	115	.97	400		CWLE	Shaded Pole	5/16" x 3-1/4"	3-3/8"	2-3/4"		AA2P026N	

**Miller**



HP	RPM	Speeds	Volts	Amps	Stock No.	Alt.	Rot.	Capacitor	Shaft Diameter & Length	Motor Dia.	"A" Dim.	Conn. Dia. No.	Cross Reference	Notes
1/50	3000	1	115	.77	512		CWLE	Shaded Pole	Blower	3-3/8"	5-1/4"		303875	
1/40	3000	1	115	.83	335		CWLE	Shaded Pole	5/16" x 1-1/2"	3-3/8"	4-3/4"		301544	
1/7	1050	1	115	5.2	326		CCWLE	Shaded Pole	1/2" x 3-1/4"	5"	3-1/2"		301543	1
1/5	1070	1	115	4.8	689		CCWLE	Shaded Pole	1/2" x 5-3/4"	5"	3-3/4"		305313	

**Miller/LSI/Home**



HP	RPM	Speeds	Volts	Amps	Stock No.	Alt.	Rot.	Capacitor	Shaft Diameter & Length	Motor Dia.	"A" Dim.	Conn. Dia. No.	Cross Reference	Notes
1/7	1050	1	115	4.7	OML6418		CCWLE	Shaded Pole	1/2" x 3-7/16"	5"	3 3/8"	84	326 D156 3M601 322P260 DA3F053 DA3F623	1
1/5	1050	1	115	6.0	OML6433		CCWLE	Shaded Pole	1/2" x 5-7/8"	5"	3-13/16"	84		2
1/5	1050	1	115	6.6	OML6435		CCWLE	Shaded Pole	1/2" x 3-5/8"	5"	4-3/8"	84		3

- Notes:**  
 1. Supplied with lead and plug assembly  
 2. 8.26" bolt circle; .28" diameter mounting holes  
 3. 10.19" bolt circle; .28" diameter mounting holes

